

**MODIFICATION TO STABILIZE IDLE AFTER RAPID THROTTLE LIFT
ON MODIFIED 350Z AND G35 WHEN IDLE ADJUSTMENTS ARE NOT
AVAILABLE THROUGH CONSULT**

