



**CORRECT POSITIONS FOR
VQ37 CAM ENCODERS ON
PHASERS**

**VQ37 CAM ENCODERS ARE PRESS FIT
ONTO PHASERS AND ARE KNOWN TO
ROTATE POSITIONS CAUSING A CAM
TIMING ERROR CODE AND POOR
RUNNING CONDITIONS.**

