



MODIFIED EARLY TYPE VQ HR INTAKE CAM
to use (13012-9N00A) 75mm long bolt to
relieve stress on front journal oil groove / hole.

